

SAFETY RECALL

BRAIDED HIGH PRESSURE HOSE RECALL

**HOSE CAN BURST AND SEPERATE AT CRIMP FITTING
CAUSING BREATHING AIR/GAS TO BE LET OUT OF TANK AT UNCONTROLLED RATE
AND MAY RESULT IN SEVERE INJURY OR DEATH DUE TO DROWNING**

Note this recall applies only to the specific lots of BRAIDED HIGH PRESSURE (HP) SCUBA hoses that are intended for use with submersible pressure gauges (SPG) and other non-diving applications.

Rather than wait for the CPSC recall to go into effect, and while only a very small number of hoses have actually been returned with this defect, we are proceeding with an abundance of caution to notify all retail accounts of Trident, other re-sellers and consumers who may have purchased these hoses to do the following:


Examine your BRAIDED high pressure hose male fitting that screws into the regulator first stage. The hex nut is stamped with a manufacturing date code. ONLY the following manufacturing date codes on HP HOSES are subject to recall:

Identification of hoses:

Black, Blue, Yellow or Green nylon BRAIDED outer covering on HP hose

**This only involves
BRAIDED High Pressure hoses with the following date stamps
that are located on the male hose end hex head:**

T0811, T0911, T1011, T1111, T0212, T0312



If your HP (high pressure) hose has any of the above date code stamps immediately remove the hose from service, and return to Trident for replacement

**Fill out the return authorization form at
WWW.TRIDENTDIVE.COM and return the hose to Trident Diving Equipment**

To receive a replacement hose, complete the form at www.tridentdive.com and return the hose to:

Trident Diving Equipment, 9616 Owensmouth Ave, Chatsworth, CA 91311

No packaging or proof of purchase is required to receive replacement hoses